

1983 Index

A

- A.R. Wright Co., Sep: 75**
 Abex, Aug: 56
 A-body wagons, Sep: 24
 Accelerator pump, backfire-caused damage, May: 6
 Accord, Jan: 52; Dec: 54
 Accumulator pressure leakage, Jul: 30
 AC-Delco, Feb: 53, 60; Mar: 58; Apr: 37; Nov: 36
 AC PF25 filter counterfeits, Apr: 62
 Aftermarket, Jan: 55
 Air bags, Oct: 10, 50-51
Air conditioning, Jun: 14-19
 compressors, Jun: 19, 56
 cycling clutch
 orifice tube, Jul: 60-62
 switch, Jun: 16-17
 front/rear, Jun: 19
 in GM's, May: 23-28; Jun: 16-19, 56
 in Skylark, Apr: 62
 solenoid, Jul: 21-22
 specs, Aug: 78
 in Sportsman, Jun: 19
 spring lock couplings, May: 90; Jun: 15-16
 vacuum pump test, Jun: 19
 in Voyagers, Jun: 19
Air Injection Reactor(AIR), Jun: 30, 59-61
Alliance (AMC), May: 90; Sep: 29; Nov: 56
 Allied Corporation, Apr: 45
 Allstate Insurance, Apr: 38
 All-Test, Inc., Oct: 43
 Aluminum, Mar: 57; Oct: 33-34
 Amco, Apr: 45
 American Automobile Association (AAA), Oct: 63; Dec: 46
 American Gas Association(AGA), Feb: 58
American Motors Corporation (AMC / Jeep/Renault)
 Alliance, May: 90; Sep: 29; Nov: 56
 CJ-5 discontinuation, Jun: 54

- Concord, Jun: 54
 diesel models, Feb: 55
 discontinued models, Jun: 54
Encore ('84), Sep: 29
 ignition timing procedure, Mar: 41
 Jeep ('81), Mar: 68, 72; Sep: 30, 70
 1984 models, Sep: 29-30, 70
 small truck planned by, Jun: 54
Spirit, discontinuation of, Jun: 54
 transmission fluid for, Sep: 32
 Amoco, Jan: 51
 Anaerobic gaskets, Dec: 23-25
 Antifreeze, May: 12, 77; Oct: 34
 AP Parts Company, Nov: 50
 ARCO, Jan: 51; Mar: 57
Aries (Dodge)
 chuckling noise, Sep: 88
 front suspension noise, Jun: 35
 rear brake noise, Jun: 66-67
 transaxle problems, Oct: 60
Arrow Achievement Award recipients, Dec: 44-45
Arrow Automotive Industries, Apr: 37; Dec: 47
Arrow Pickup, upper control arm replace, Feb: 80
ASC, May: 67
Association of Diesel Specialists, Jul: 55
 Atlantic Richfield, Jan: 51; Mar: 57
Audi, Jul: 59, Sep: 32
 Audi 5000S, Jun: 47
Automobile Mechanic Training Evaluation Project(AMTEP), Apr: 43
Automotive Parts & Accessories Association(APAA), Feb: 53; Apr: 44; Sep: 61; Oct: 66
Automotive Service Councils, Inc., Jun: 43
Automotive Service Excellence(ASE), Jul: 36
Automotive Warehouse Distributors Association(AWDA), Sep: 76
Automotive Wholesalers of Illinois, Mar: 59

B

- Backpressure, Sep: 64; Oct: 49**
 Balance shaft system, Sep: 61
Batteries
 Delco Freedom, Feb: 60-61; Nov: 36
 load testing, Feb: 60-61
 PVC caps for, Mar: 84-85
 recharging, Feb: 60-61
Torque Starter, Jun: 68
Bearings, Sep: 48-49; Oct: 58
Bench bleeding, Dec: 28-29
Bendix Corp, Apr: 45; Aug: 56
Bendix SWC ('84), Oct: 63
Berger, Robert L., Aug: 64
Bidwell, Ben, Sep: 61
Bill Penn Memorial Scholarship, Nov: 50
 Black box ignition in '84 Buicks, Jul: 36
BMW, Sep: 32
Body work, Mar: 53-55
Booker, Lawrence, E., Aug: 63
Booklets. See Catalogs, manuals, guides, booklets
Bowes Seal Fast Corporation, Dec: 46
Brake(s)
 back-up, Sep: 75
 binding, in Aspen ('77), May: 8
 bleeding, Dec: 27-32
 caliper, in Fairmont/Zephyr, Jun: 66
 charts for, May: 85
 do-it-yourself jobs, Apr: 63
 disc, Sep: 88; Oct: 61, 78; Dec: 49
 lining, Aug: 14-22, 55-56
 rear, noise, Jun: 66-67
 service standards and procedures, lack of, Aug: 6-7
 steel wool, Oct: 64
Brake fluids, silicone, Dec: 29-32
Brava ('80), Dec: 53
Buffum, John, Jan: 51
Buick
 all-front wheel drive lineup, Nov: 35
 Capital Electronic Product Center, Apr: 43

1983 Index

Century ('82-'83) tune up specs, Jan: 74
 Delta 88 production, Jul: 38
 Electra ('80), Dec: 49
 electronic products of, Nov: 41-44
 free advice by phone service, Sep: 62
 fuel injection system, Jul: 36; Sep: 21
 ignition systems
 black box, Jul: 36
 distributorless, Sep: 21; Nov: 28-32, 45-48
 LaSabre ('80), blower motor, Dec: 49
 light throttle detonation, Jul: 57
 Regal, Jul: 37
 Skylark. *See Skylark (Buick)*
 starting motor specs, May: 106
 Bur, Thomas G., Aug: 63
 Business interruption insurance, Nov: 57-58
 Bussman Division of McGraw-Edison, Apr: 45

C

C-3 (GM) engine control system
 in Cutlass ('81), May: 10, 75
 tester, Apr: 22-25, 52-57; Dec: 63-64
 basic functions, Apr: 22-25, 52-55
 design, Apr: 55-57
Carbolet, Dec: 44
Cadillac
 cold engine noise, Jun: 66
 Eldorado Touring Coupe ('83), Jan: 51
 front/rear wheel drive models, Aug: 54
 front-wheel drive limo, Sep: 76
 ignition timing, Mar: 36-37
 increase in new cars, May: 85
 manifold absolute pressure(MAP)
 sensor line icing, Jan: 61
 1983 sales, Dec: 46
 power steering/power brake failure,
 May: 16, 67
 Sedan DeVille alignment, Jan: 8-9
CAFE(corporate average fuel
 economy), Feb: 48; Jun: 53; Aug:
 51; Sep: 60; Oct: 42; Nov: 37
Caldwell, Phillip, Aug: 63
California
 car sales in, Jul: 38
 design studios in, Jul: 38
 as import sales predictor, Jan: 17-18
 maximum allowable HC and CO
 limits, Mar: 90
 tax laws, conflict in, Jun: 54
Calipers, Jun: 70
 dust boots, installation of, Feb: 31-39
Camry ('83), Mar: 57
 Canadian government, Feb: 54
Capri (Mercury)
 brake caliper changes, Jun: 66

fluid checking, Nov: 56
 stalling while parking, Dec: 48
Caprice ('81) diesel, Dec: 49
Carburetors
 adjustment specs, Mar: 90; Apr: 70;
 Dec: 70
 gasket, Feb: 68
 mounting, Feb: 9, 19
 seminar on, Nov: 50
 subsystems and deceleration valves,
 Jul: 21-24
 two barrel, rebuilding, Aug: 24-32
variable venturi, Mar: 18-29
 adjustments, Mar: 22-24
 reassembly, Mar: 26-29
 teardown procedure, Mar: 21-22
Car Care Council(CCC), Sep: 78
Car Carrier, Jul: 65
Carter Automotive Division, Aug: 61
Catalogs, manuals, guides, booklets
 alignment types poster, Nov: 67
Bearing Failure Trouble-Shooting
 Guide, Sep: 100
Borg-Warner Brand ignition catalog,
 supplement, Apr: 64
brakes, Jun: 69
 EIS Brake Manual, Jul: 68
 service manual, Mar: 82
Carter Climatrol Cooling and Heating
 Parts, Aug: 68
Carter Precision Remanufactured
 Electrical Components, Dec: 62
 calipers catalog, Jan: 63
 cap and thermostat catalog, Jan: 64
 equipment catalog, Mar: 84
Import/Domestic Cylinder Head
 Specification Manual, Oct: 71
 imported parts catalog, May: 101
 " Lamp & Flasher Replacement
 Guide" (update), Oct: 71
Mighty Distributing System of
 America technical manual, Jul:
 67
Motor Auto Repair Manual 1984,
 Oct: 68; Dec: 60
Motor Emission Control Manual,
 Mar: 75, 90; Sep: 94; Oct: 39
Motor Imported Car Parts & Time
 Guide, Aug: 67; Oct: 69
Motor Imported Car Repair Manual,
 Jul: 65
Motor Parts & Time Guide 1984,
 Nov: 61
Motor Truck & Diesel Repair
 Manual, Apr: 64
Motor Wiring Diagram Manual,
 Jun: 71
 "New and Remanufactured Clutches
 for Passenger Cars and Light
 Trucks" (Cat. No., C-83; BWD
 Automotive Corporation), Oct: 75
OTC Tools & Equipment Supple-
 ment, Aug: 67
 parts catalog, Feb: 71
 "Quick Course in Car Care—Cooling
 System," Sep: 98

Raybestos Brake Products Catalog
 Supplement, Dec: 58
 remanufactured injection pumps and
 nozzles catalog, Dec: 62
 Saab service bulletin no. 04/83-624,
 Sep: 1
Strut Cartridges and Assemblies for
 Domestic and Import Passenger
 Cars, Nov: 64
 suspension systems poster, Nov: 67
TRW Automatic Transmission Parts
 catalog, Dec: 67
Catalytic converters, Oct: 48; Dec: 14
Center for Auto Safety(CAS), Oct: 41
Ceres three-wheeler, Jun: 41
Champion Parts Rebuilders, Inc., Mar:
 59; Sep: 79
Champion Spark Plug Co., Jul: 55;
 Oct: 63
Chevette (Chevrolet)
 fuel system problems, Aug: 10-11;
 Nov: 10
 starting motor, tune up, and wheel
 alignment specs, May: 106
 steering wheel shakiness, Feb: 8
Chevrolet
 Caprice ('81) diesel, Dec: 49
 Celebrity ('82-'83) tune up specs
 Jan: '74
 Chevette. *See Chevette (Chevrolet)*
 Citation, Jun: 35, 36
 Corvette. *See Corvette (Chevrolet)*
 dwell reading, Oct: 61
 EGR valves, Sep: 88
 franchising by, Jun: 51
 Impala ('81) diesel diode service,
 Dec: 49
 Malibu. *See Malibu (Chevrolet)*
 manifolds, intake adapter, for, Mar:
 87
 M-van introduction, Sep: 59
 Nova ('68), oil dilution, Apr: 8-9
 3.8 liter cold driveability problems,
 Dec: 12-13
 truck sales position, May: 67
 V6 engine, Mar: 87-88
 wheel alignmnt for '69-'70s, Oct: 78
 Chicago Rawhide, Apr: 45
 Choke, electric and hot air, Jul: 22-23
Chrysler
 A-460 transaxle, Oct: 60
 accelerator pump adjust, May: 91
 aspirator valve failure, Nov: 18-19
 balance shaft system, Sep: 61
 cold driveability problems, Aug: 10
 competition with GM/Toyota joint
 venture car, May: 83
 Cordoba and Mirada discontinuation,
 Jun: 54
 design studios, Jul: 38
 diesel program cancellation, Feb: 54
 digital-circuit ignition components
 and RF interference, Apr: 62
 engine oil leaks, Jan: 62-63
 400, Sep: 88
 front wheel drive, Jun: 36; Jul: 57,

70; Aug: 75
fuel injection, electronic, Nov: 21-26
GM product line-up and, Apr: 36
gypsy packagers, suit against, Dec: 35

ignition timing procedures, Mar: 37-38

LeBaron, Sep: 88
marketing strategy, Oct: 44

Mitsubishi relationship, Jan: 28

1984 models, Jul: 38; Sep: 25-26

1983 models, Feb: 64

partnership deals of, Sep: 61

problems due to profit, Sep: 59

ranking goal of, Nov: 36

steering knuckle replace, Mar: 90
with throttle body injection(TBI), Sep: 26

T-115 Van and Wagon, Sep: 25

transaxle, manual, Feb: 64

transmission fluid for, Sep: 32

trucks, hesitation or sag, Dec: 49

two-passenger model, Jul: 36; Oct: 44

2.2-liter engines, Oct: 61

unemployment figures and, Oct: 43

valve spring change, Aug: 75

Vega ('77) overheating, Oct: 16, 53

-VW deal collapse, Oct: 42

CIS. See Continuous injection system

Clutch

installation, Sep: 50

release bearing noise test, Sep: 49

repair tips, Sep: 45-50

self-adjusting, in Starlet ('81-'83), Dec: 53

squeak test, Sep: 49

Colt ('80), Dec: 14

Compounding, Mar: 54-55

Compressors

a/c, Jun: 19, 56

MacPherson strut, Feb: 71

Computerization, Jan: 56; Feb: 47; Mar: 64; Jul: 68

Computer listing, Jul: 53

Consumer agencies, Jun: 52

Contact lenses, use during welding, Jun: 52; Jul: 37

Continuous injection system(CIS), Jul: 27-32

hot start problems, Jul: 28-29; Oct: 12, 52

Convertibles, Oct: 64

Coolant, worn out, Oct: 33-36, 55

Cooling system sealants, Jun: 69

Corvette (Chevrolet)

disc brake service, Oct: 61

1983 model, Feb: 25-27, 42, 66;

May: 85; Jun: 52

Cosworth racing engine, May: 60-62

Counterfeiting, May: 85; Jun: 6; Sep: 61; Dec: 34-35

Credit cards, Apr: 6, 66

Cruise control, electronic, Nov: 42

Customers, flexibility with, Jun: 12

Cylinder power balance test, May: 78-79

D

D50 upper control arm replace, Feb: 80

Dallas Grand Prix, Nov: 50-51

Dana Corporation, May: 67; Jul: 58

Datsun, Sep: 32; Dec: 54. See also Nissan

Dealer(s)

consumer agencies and, Jun: 52
diesel-to-gas engine swapping by, Nov: 37

dual, Oct: 43

foreign car makers and, May: 85

possible Chevrolet-Toyota cooperation, Jul: 37

price increases and, Jul: 35

service recommendations, Mar: 64

Dealer Advertising Awards, Dec: 46

Delaney, Michael J., Aug: 63

Detroit

crisis in, theories of, Jan: 6-7

excess plant capacity of, Jan: 57

proprietary tools elimination by, Aug: 51

tool makers and, Jan: 55

Detroit Grand Prix, Jul: 38

Dexron II, Sep: 32

Diesel engines. See Engines, diesel

Diesel fuel, contaminated, Dec: 48

Dieseling, Jul: 21

DiGard racing team, Aug: 36-47, 57-58

Distributor

HEI-equipped, May: 91

pickups, in '78-'79 Omni/Horizon, Feb: 62

rotors, in Toyota, Sep: 82

Dodge

Aries. See Aries (Dodge)

Aspen ('77), Feb: 8; May: 8

Mirada, discontinuation of, Jun: 54

Monaco ('77), handling, Feb: 8-9

Omni. See Omni (Dodge)

pickups, diesel engine for, Oct: 66

pistons, pins, rings, crankshaft and bearing specs, Nov: 70

Rampage, Jul: 41-48

vans ('79-'82), inoperative starter relay, Jun: 67

Dorman Products, Dec: 46

Drive train, Tempo/Topaz, Apr: 28-31, 59

Du Pont Company, Dec: 46

Dust boots, Feb: 32-39; Mar: 77

E

Early Fuel Evaporation (EFE)

system, Jun: 26-30, 58-59

Echlin Inc., Feb: 47

"Editor's Report"

accelerator pump, backfire-caused damage, May: 6

brake system standards and procedures, lack of, Aug: 6-7

competition with mass merchandisers and tire chains, Jul: 6, 51

Detroit's crisis, lessons for after-market, Jan: 6-7

factory engineer's ignorance of service business, May: 6, 72

Gun Control Act of 1968, Dec: 10-11

gypsy parts update, Jun: 6

lifetime service guarantees, Jun: 6

mechanics' working conditions, Feb: 6-7

passive restraints, Oct: 10, 50-51

plastic engines, Nov: 8-9

protectionist legislation, Mar: 8

refusal to pay credit card charges, Apr: 6, 66

X-car recall, Sep: 6, 63

Edmund, Stan, Aug: 64

EGR valves, Feb: 15-22, 41; May: 20; Sep: 88

EIS, Aug: 56

Electrical systems, seminar on, Nov: 50

Electronic Engine Control(EEC), Mar: 38-41; Jun: 10

Emission controls in GM cars. See General Motors Corporation (GMC), emissions controls systems

Engines

aluminum, Nov: 36

Chevy V6, Mar: 87-88

Chrysler, oil leaks in, Jan: 62-63

compartment component tagging, proposed, Mar: 64

Cosworth racing, May: 60-62

decreased development of, Jan: 57

diesel direct injection, Nov: 50

-to-gas swapping, Nov: 37

head gaskets for, May: 38-39; Aug: 75

hot starting problems, Feb: 62-64

piston, pins, rings, camshaft and bearing specs, Nov: 70

for small pickups, Oct: 66

for Tempo/Topaz, Jul: 38

tightening specs, Nov: 70

turbocharging, Apr: 14-18, 46-50

valve specs, Dec: 70

Ford V8, Feb: 62; May: 58

460 cid main bearing knock, Aug: 70

Japanese, kits for, Jan: 73

Honda, rebuilding, Oct: 27-32, 56-58

Offenhauser, May: 57-60

plastic, Nov: 8-9

for Tempo/Topaz, Jan: 58; Jul: 38; Sep: 62

turbocharged, Sep: 24, 25-26

3.8 liter, spark plug change, Feb: 62

tri-fuel, Jul: 37

2.2 liter oversize camshaft markings, Oct: 61

2.5 liter gear noise, Nov: 56

1983 Index

Equipment. See Tools, repair kits, equipment
Equipment suppliers, computer-aided service and, Mar: 64
Escort (Ford)
 brake booster replacement, Jul: 57
 brake specs, Jun: 78
 diesel model, Sep: 29
 master cylinder replace, Jul: 70
 piston markings, Oct: 61
 power, lack of, Sep: 88
 radiator of, May: 41-42
 rear wheel bearing adjust, Aug: 78
 steering wheel return, Jul: 57
 turbocharged, Sep: 28-29
Evaporative Control Systems(ECS), Jan: 44-46
 valves, May: 20; Sept: 88
Evaporators, GM, Jun: 16-19
Exhaust Gas Recirculation(EGR) system, Feb: 15-22, 41
Exhaust repair market, Mar: 60
Exhaust systems
 clamping vs. welding in, Oct: 48
 restricted, Dec: 48
 small car, Oct: 47-49
 Toyota, Mar: 47
EXP (Ford)
 brake specs, Jun: 78
 continuation of, Jul: 35
 master cylinder replace, Jul: 70
 radiator of, May: 41-42
 rear wheel bearing adjust, Aug: 78
 turbocharged version of, Jul: 53
 Exxon, Jan: 51

F

Facom Tools, Inc., May: 678
Fairmont (Ford)
 brake caliper changes, Jun: 66
 driveability and stumble problem, Apr: 8; Jul: 10
 stalling while parking, Dec: 48
Fair Practices in Automotive Products Act (H.R. 5133), Mar: 8
Fan belts, Apr: 44
Faulkner, Dale, Aug: 64
Federal-Mogul, May: 86
Fel-Pro, Dec: 45
Felt, needle, Sep: 32-41
Fender covers, Feb: 71
Fiat
 timing belt replace, Feb: 80
 transmission fluid for, Sep: 32
"Field Fixes"
 batteries, recharging, Feb: 60-61
 Ford cycling clutch orifice tube a/c, Jul: 60-62
 oil leaks, Jan: 62-63; Sep: 92
 spark knock, Mar: 70, 73
 THM leak diagnosis, Dec: 55
 Toyota automatic transmissions, May: 94-96; Jun: 63-65

Fiesta (Ford)
 on-car wheel balancing, Jul: 59
 power and mpg loss, Dec: 54
 turn signal flashers, Sep: 82
Filters
 AC PF25, counterfeit, Apr: 62
 oil, in Toyotas, Mar: 50
 transmission, Sep: 31-41
Firestone, Feb: 48; Apr: 37; May: 83; Dec: 36
Fleet operators, Jan: 52
Float bowl, fuel loss in, Jul: 10
Florida Automotive Service Councils, Inc., Mar: 59; Nov: 51-53
Flywheel inspection, Sep: 49-50
FMC, Dec: 47
Ford, Edsel Bryant, II, Sep: 29
Ford
 air conditioners, May: 90; Jun: 15-17, 56; Jul: 60-62
 balance shaft system, Sep: 61
 big car sales, reaction to, Aug: 51
 CAFE(corporate average fuel economy) requirement and, Jun: 53; Aug: 51; Sep: 60
 clutch repair tips for '81s, Sep: 49
 counterfeiting problems, Dec: 34
 curtailment of projects, Feb: 54
 diesel model offerings, Feb: 55
 detonation problems in '80s, Sep: 90
 Econoline, Jun: 55
Electronic Engine Control(EEC), Mar: 38-41; Jun: 10
engines. See **Ford engines**
Escort. See **Escort (Ford)**
EXP. See **EXP (Ford)**
F350 ('79), fuel vaporization problems, Nov: 10-15
Fairmont. See **Fairmont (Ford)**
Fiesta. See **Fiesta (Ford)**
FM radio interference in '77-'81s, Oct: 61
Fram vs., Jun: 53
 fuel economy, Mar: 66
 fuel injection systems, electronic, Nov: 28
 full-lock turn stall in '78-'81s, Sep: 90-91
GM product line up and, Apr: 36
Granada, Jun: 36; Dec: 48, 49
 ignition timing procedures, Mar: 38-40
LTD, Jul: 36
LTS-9000 armored truck, Jun: 41
 methane car project, Feb: 58-59
Mini Van, May: 68
 with NASCAR blocks, Mar: 86-87
 1984 models (domestic), Sep: 26-29, 59
Olds' challenge to, Nov: 37
parts
 division hotline, Jun: 41
 interchangeable, Apr: 38
 power rack and pinion replacement, Mar: 68
 overseas sources, interest in, Nov: 35
 problems due to profits, Sep: 59
 robots, use of, Jul: 20
 rust prevention process, May: 86
 San Jose plant closing, Jan: 56
 service, Mar: 63; May: 84; Jun: 6, 41, 51; Oct: 22
 simulated voice alerts cancellation, Sep: 60
spark retard module, Mar: 40
strut diagnosis, Jan: 61
Tempo. See **Tempo (Ford)**
Tempo/Topaz support, Nov: 53
 test drive program, Dec: 46-47
Thunderbird. See **Thunderbird (Ford)**
 transmission fluid for, Sep: 32
 unemployment figures and, Oct: 43
 van ('78), fuel vaporization problems, Nov: 10-15
 wheel alignment specs, Jan: 74
Ford engines
 460 cid ('75-'77), main bearing knock, Aug: 75
 planned optional, Jun: 52
 Tempo/Topaz diesel, Jul: 38
 3.8 liter, spark plug change in, Feb: 62
 V8, Feb: 62; May: 58
Foreign car makers, dealers and, May: 85. See also Imported cars
 "4-Wheeling With Ford," Apr: 37
Fram, Jun: 53; Aug: 53
 Front-wheel vs. rear-wheel drive, Jul: 37
Fuego Turbo, wiring abrasion, Dec: 54
Fuel
 CIS hot start problems and, Jul: 29-32
 diesel, Apr: 65; Dec: 48
 hydrogen, Mar: 88
 loss, in float bowl, Jul: 10
 methane, Feb: 58-59
 price of, Apr: 35; Jun: 41
 Fuel distributor leakage, Jul: 32
Fuel heaters, Apr: 65
Fuel injection systems
 Buick, Jul: 36; Sep: 21
 continuous(CIS), Jul: 27-32
 direct, in diesels, Nov: 50
 electronic, Sep: 21, 28; Nov: 21-26, 41, 42
 in GMs, Sep: 24
 throttle body(TBI), Mar: 33; Sep: 26
 Fujitsu Fanuc, Ltd., Jul: 20

G

Gannon, Kevin, D., Jul: 55
Garrett Corporation, Feb: 47
Gaskets
 anaerobic, Dec: 23-25
 carburetor, Feb: 68

1983 Index

compounds, Jan: 72-73; Apr: 64
 head, May: 31-39
 chemical sealants, May: 39
 in diesel engines, May: 38-39
 of Hondas, Oct: 57-58
 installation tips, May: 33-38
 retorquing, Oct: 52
 remover, Jun: 69
 soft, Dec: 23-25
Gasoline nozzle notch device, Jan: 52
Gasoline vapors, danger of, Oct: 63
General electric, Sep: 76
General Motors Corporation(GMC)
 A-body wagons, Sep: 74
 air conditioning, May: 23-28; Jun: 16-19, 56
 audio offerings, Sep: 79
C-3 computer diagnostic system
 testers, Apr: 21-25; May: 10, 75;
 Dec: 63-64
CAFE(corporation average fuel economy) and, Feb: 48; Jun: 53;
 Sep: 60; Oct: 42
C-car production delay, Oct: 41
 computer command control, Jul: 70
 consolidation of manufacturing, Mar: 65
 curtailment of projects, Feb: 54
 design studios, Jul: 38
 diesel fuel filter test, Sep: 91
 diesel models, Feb: 55; Dec: 49
 ECM malfunction in '82-'83 fuel injection models, Sep: 81
 emissions controls systems
 Air Injection Reactor(AIR), Jun: 30, 59-61
 carburetor subsystems and deceleration valves, Jul: 21-24
Early Fuel Evaporation(EFE), Jun: 26-30, 58-59
Exhaust Gas Recirculation(EGR), Feb: 15-22, 41
Positive Crankcase Ventilation (PCV), Jan: 41-44
 preheated intake air system, Jan: 46-49
Pulse Air Injection Reactor(PAIR), Jun: 30, 59-61
 vacuum spark control devices, Oct: 37-39
engines
 aluminum, Nov: 36
 5.7-liter diesel, head gasket changes, Aug: 75
 tri-fuel, development of, Jul: 37
 2.5-liter, timing gear noise, Nov: 56
 evaporators, Jun: 16-19
 exclusive bodies by division, Feb: 53; Oct: 44
 fuel injection system, Sep: 24
 ignition systems, Mar: 33-36; May: 91, Jul: 36
 import restrictions, position on, Nov: 35
 in-company suppliers and, Jan: 58
 N-cars, Nov: 53

New York City Transit Authority
 bus contract of, Feb: 47
 1984 models, Sep: 20-24
 overseas parts sources and, Nov: 35
 pickups and 4 X 4 recall, Feb: 64
 product lineup, Apr: 36
 problems due to profits, Sep: 59
 reaction to big car sales and, Aug: 51
 restricted exhaust in '82-'83s, Dec: 48
 robots, use by, Jul: 20
 roller hydraulic lifter, Dec: 51-52
 search for fuel economy regulation
 loopholes, Aug: 51
 service, May: 86; Aug: 53; Nov: 37
 T-cars, Feb: 55
 transmissions, Apr: 62; Sep: 32; Oct: 61; Dec: 49
 unemployment figures and, Oct: 43
X-body cars. See **X-cars (GM)**
General Motors Corporation-Toyota partnership
 Chrysler and, May: 83
 consequences of, Dec: 34-35
 "foreign imports" and, Apr: 38
 in-house reactions to, Sep: 60
 Japanese production secrets and, Apr: 36
 negotiations of, Jan: 57
 parts business and, Apr: 35
Gillis, Alan, Aug: 63
GNB Batteries (company), May: 67
Goodyear, May: 67; Jul: 54
Green Light Company, Sep: 60
Guaranteed Parts Company, Aug: 62; Sep: 75
Guarantees
 check, Mar: 67
 lifetime service, Mar: 63; May: 84; Jun: 6
Guides. See **Catalogs, manuals, guides, booklets**
Guns, law and, Dec: 10-11, 18-21

H

Handbook, 60th ed. — '83
 brake data, cars ('80-'83), 67-72
 cooling system and capacity data ('80-'83), cars, 86-101
 American Motors, 86
 Buick, 86-87
 Cadillac, 88
 Chevrolet, 88-94
 Chrysler, 94, 95-96
 Dodge, 95
 Ford, 96-98
 Lincoln, 98-99
 Mercury, 96-98
 Oldsmobile, 99-100
 Pontiac, 100-101
 engine torque wrench data ('80-'83), 112-115
 cars, 112-113
 trucks, 114-115
farm tractor tune-up, 121-127
 new products, 140-148
 piston and rod assembly ('80-'83), 73-81
 cars, 73-76
 trucks, 77-81
 pushing and towing automatic drive cars, 139
spark plug application chart, 128-137
tune up data, cars ('80-'83), 3-53
 American Motors, 3-4
 Audi, 49-50
 Buick, 5-6, 18-19
 Cadillac, 7
 Chevrolet, 10-18
 Chrysler, 20-24
 Datsun/Nissan, 43-45
 Dodge, 45
 Fiat, 46
 Ford, 25-34, 46
 Honda, 46-47
 Isuzu, 47
 Jaguar, 47
 Lincoln Continental, 35-36
 Mazda, 47-48
 Mercedes-Benz, 48
 Mercury, 25-34
 MG, 48
 Oldsmobile, 37-38
 Olds Cutlass Ciera, 18
 Olds Starfire, 19
 Peugeot, 48
 Plymouth, 49
 Pontiac, 18-19, 39-42
 Porsche, 49-50
 Renault, 50
 Saab, 50
 Subaru, 50-51
 Toyota, 51-52
 Triumph, 52
 Versailles, 35-36
 Volkswagen, 52-53
 Volvo, 53
tune up data, trucks ('80-'83), 54-56
 Chevrolet, 54-57
 Dodge, 58-60
 Ford, 60-65
 GMC, 54-57
 international, 65
 Jeep, 65-66
 Plymouth, 58-60
 valve timing marks ('80-'83), 83-85
 wheel alignment data ('80-'83), cars, 102-106, 107-111
H.K. Porter, Aug: 56
Harabosky, Serge, Oct: 32
Head gaskets, May: 31-39
 chemical sealants, May: 39
 in diesel engines, May: 38-39
 of Hondas, Oct: 57-58
 installation tips, May: 33-38
 retorquing, Oct: 52
Heaters, fuel, Apr: 65
Hein-Werner, Mar: 66

1983 Index

Henschen, Mark M., Jul: 54
Hertz, limited warranties of, Mar: 58
Holley 6520 adjustment specs, Jan: 74
Holtzberg, Matthew, Nov: 8-9
Home-office deductions, May: 102-103
Honda
auxiliary valve, plugged, Oct: 32, 56
bearing matching for, Oct: 58
camshaft, Oct: 29-32
engine rebuilding, Oct: 27-32, 56-58
gauge malfunction, Sep: 82
head gaskets of, Oct: 57-58
oil consumption of, Oct: 56
oil pump problems, Oct: 57
oil strainer in, Oct: 38
powerplant applications, Oct: 29
radial tire vibration, Jun: 37
rod bearing problems, Oct: 56-57
servicing, Jan: 31-39
specialty equipment, Oct: 32
thrust bearing problems, Oct: 57
transmission fluid for, Sep: 32
Honda Accord, Dec: 54
U.S. built, Jan: 52
Honda Civic CRX, Nov: 50
Horizon
carburetor mounting, Feb: 19
disc brake piston, Sep: 88
disc brake service, Dec: 49
distributor pickup, Feb: 62
front suspension noise, Jun: 25
isolator plates, Jul: 10-11
mileage problems, Mar: 12, 56
rear brake noise, Jun: 66-67
throttle shaft wear, Oct: 12
transaxle problems, Oct: 60
vacuum leak, Jul: 10-11
wheel bearing failure, Jan: 61
Hoses, sales of, Apr: 44
Hot start problems, CIS, Oct: 12, 52
Hot-start relay, Jul: 32
Hunter Engineering, Dec: 46
Hydraulic lifters, Feb: 62; Dec: 51-52
Hydrogen fuel, Mar: 88
Hydrometer, Freedom battery's, Feb: 61
Hyundai, Dec: 44

VW, Mar: 41
Imported cars
1983 models, Jan: 16-28
California as predictor of sales of, Jan: 17-18
general sales trends, Jan: 18
Japanese sales, Dec: 45
Mazda, Jan: 22-26
Mitsubishi, Jan: 28
Nissan, Jan: 20-21
Porsche, Jan: 27-28
Toyota, Jan: 20
Volkswagen, Jan: 26-27
restrictions on, Aug: 52; Nov: 35
Impulse coupe, (Isuzu), Aug: 61
Independent Automotive Service Assn., Mar: 59; Jun: 43
Independents, Mar: 60; Sep: 60-61
Indianapolis 500, May: 50-53, 57-62
Insurance
Allstate, Apr: 38
auto, Mar: 57
business interruption, Nov: 57-58
radial tires and, Mar: 57
vehicle theft and, Feb: 54
Investment tax credit, Sep: 83, 87
Iococca, Lee, Sep: 61
Isuzu, transmission fluid for, Sep: 32
impulse coupe, Aug: 61

LeCar discontinuation, Jun: 54
Lee Filter, Sep: 79
Legislation, local content, Mar: 8; Aug: 52
LeSabre ('80), blower motor, Dec: 49
Lifters, hydraulic, Feb: 62; Dec: 51-52
Lincoln
full-lock turn stall, Sep: 90-91
Mark IV, air suspension, Apr: 45
Mark VII, Jul: 55, Sep: 26-28
rack and pinion replacement parts, Mar: 68
strut diagnosis, Jan: 61
Littlefuse, Inc., May: 85
LN7 (Mercury)
brake specs, Jun: 78
discontinuation of, Jul: 35
Master cylinder replace, Jul: 70
radiator of, May: 41-42
rear wheel bearing adjust, Aug: 78
Loans, low interest, Jun: 53
"Longest Day of Nelson Ledges," Aug: 61
Loss coverage, Feb: 73-74
Lotus Eclat 2 + 2, Jan: 51
Lotus Performance Cars, Jul: 54
Lotus racing team, Mar: 57
LUV ('74) pickup linkage, Jan: 9
Lynx (Mercury)
brake booster replace, Jul: 57
brake specs, Jun: 78
diesel, Sep: 29
master cylinder replace, Jul: 70
piston markings, Oct: 61
power, lack of, Sep: 88
radiator of, May: 41-42
rear wheel bearing adjust, Aug: 78
steering wheel return, Jul: 57

J

Jaguar, Jan: 51; Sep: 32; Dec: 46
Januar XJ6 ('83), Jan: 28

Japan
export policy of, Aug: 52
import quota on, Oct: 43
increased sales, Dec: 45
parts from, Dec: 35
production secrets, Apr: 36
success of, Jan: 6
Japan Automobile Manufacturers Association, Dec: 45
JC Penney, Mar: 65

M

McCord Gasket Division, Mar: 59

MacPherson struts
checker, Jan: 69
compressors, Feb: 71
diagnosis, Jan: 61
front assembly ID, Jun: 78
support mountings and bearings for, Apr: 65

McQuay-Norris, Dec: 47

Malibu (Chevrolet)
mixture problems in '82s, Sep: 64
pinging in '81s, Jun: 10, 55

Manuals. See Catalogs, manuals, guides, booklets

"Manual Update"

air conditioning specs, Aug: 78
Arrow Pickup upper control arm replace, Feb: 80
Buick starting motor specs, May: 106
California HC & CO limits, Mar: 90
carburetor adjustment specs, Apr: 70; Dec: 70
Celebrity ('82-'83) tune up specs,

I

Ideal Corporation, Oct: 66

Ignition systems
digital circuit, Apr: 62
distributionless, Sep: 21, 24; Nov: 28-32, 45-48
electronic, Mar: 46; Nov: 41-42
GM, Mar: 33-36; May: 91; Jul: 36, 57
timing procedures, Mar: 33-41
AMC, Mar: 41
Cadillac digital display, Mar: 36-37
Chrysler, Mar: 37-38
Ford, Mar: 38-40
GM, Mar: 33-36
Olds Misar, Mar: 37

K

Kwik-way Industries, Inc., Aug: 62-63

L

Lanair, Inc., May: 69
Lang, Allen, Aug: 64
Laser/Daytona ('84), Sep: 25
Lathrop, Ken, Aug: 63
Lawyers, Jul: 38

1983 Index

Jan: 74
 Century ('82-'83) tune up specs, Jan: 74
 Chevette starting motor, tune up, and wheel alignment specs, May: 106
 Chevrolet ('69-'70) wheel alignment procedure, Oct: 78
 Chrysler
 FWD oversize camshaft bearing ID, Jul: 70
 steering knuckle replace, Mar: 90
 D50 upper control arm replace Feb: 80
 Dayton-Walther dual piston disc brake caliper rebuild, Oct: 78
 Dodge pistons, pins, rings, crankshaft & bearings specs, Nov: 70
 Escort/EXP
 brake specs, Jun: 78
 master cylinder replace, Jul: 70
 rear wheel bearing adjust, Aug: 78
 Fiat timing belt replace, Feb: 80
 Firebird ('82-'83) radio replace, Mar: 90
 Ford wheel alignment specs, Jan: 74
 front strut assembly ID, Jun: 78
 GM computer command control, Jul: 70
 Holley 6520 adjust specs, Jan: 74
 International diesel engines
 valve specs, Dec: 70
 piston, pins, rings, crankshaft & bearings specs, Nov: 70
 tightening specs, Nov: 70
 LN7/Lynx
 brake specs, Jun: 78
 master cylinder replace, Jul: 70
 rear wheel bearing adjust, Aug: 78
 Mercury wheel alignment specs, Jan: 74
 Motorcraft model 740 carburetor adjust specs, Mar: 90
 Olds Cutlass Ciera tune up specs, Jan: 74
 Plymouth pistons, pins, rings, crankshaft, and bearings specs, Nov: 70
 Pontiac 1000 starting motor, tune up, and wheel alignment specs, May: 106
 Pontiac 6000 ('82-'83) tune up specs, Jan: 74
 Pontiac radial replace, Mar: 90
 Porsche
 cooling system and capacity data, Feb: 80
 tune up specs, Feb: 80
 Quadrajet M4M series adjust specs, Sep: 102
 Ram 50 upper control arm replace, Feb: 80
 Rochester 2SE & E2SE adjust specs, Apr: 70
 steering knuckle replace, Jun: 78
 Toyota starter replace, Nov: 70

Matsushita Electric Trading Company, Apr: 45
 Mature industry theory, Jan: 6-7
Mazda
 B2000 Sundowner ('83), Jun: 41-42
 B2200 diesel pickup, Apr: 18
 GLC ('83), Jan: 22
 1983 imported models, Jan: 22-26
 RX-7, May: 67
 626 ('83), Jan: 22-26
 transmission fluid for, Sep: 32
Mercedes-Benz
 air bag option, Oct: 10, 50-51
 discontinued models, Sep: 60
 engine preheater, Sep: 75
 transmission fluid for, Sep: 32
 turbo wastegate check, Sep: 54-56
 two-seaters, Oct: 63
Merchandisers, mass, Jul: 6, 51
Mercury
 Capri. *See Capri (Mercury)*
 Cougar, Feb: 47; Jun: 36; Dec: 48, 49
 full-lock turn stall, Sep: 90-91
 LN7. *See LN7 (Mercury)*
 Lynx. *See Lynx (Mercury)*
 Montero ('83), Mar: 57
 power rack and pinion replacement parts for '79s, Mar: 68
 strut diagnosis, Jan: 61
 Topaz. *See Topaz (Mercury)*
 wheel alignment specs, Jan: 74
 Zephyr. *See Zephyr (Mercury)*
 Methane fuel, Feb: 58-59
 MG, transmission fluid for, Sep: 32
 Mileage record, Aug: 61
 Millen, Steve, Jul: 53
 Mini-Baja West, Sep: 76
 Minit-Lube, Feb: 47
Miser (Plymouth)
 ignition timing procedures, Mar: 37
 spark knock in, Mar: 68
Mr. Gasket Co., Jul: 55
Mitsubishi
 -Chrysler relationship, Jan: 28
 Cordia ('83), Jan: 27, 28
 1983 models, Jan: 28
 Starion ('83), Jan: 26, 28
 Tredia ('83), Jan: 28
 transmission fluid for, Sep: 32
Mobile Air Conditioning Society Convention and Trade Show (MACS), Jun: 15
 Monroe, Dec: 47
Moog Automotive Training Center, Mar: 59
 Motor homes, high-mileage, Mar: 88
Motor Vehicles Manufacturers Association, The, Mar: 59
 Muffler(s), rear mounted, Oct: 48
 Muffler market, Sep: 61
Mustang (Ford)
 brake caliper changes, Jun: 66
 fluid checking, Nov: 56
 GT, Jun: 75
 stalling while parking, Dec: 48
 SVP, Sep: 28; Oct: 63-64

N

NATEF(National Automotive Technicians Education Foundation), Apr: 43
 National Association of Wholesaler-Distributors(NAW), Oct: 64
 National Automotive Parts Association (NAPA), Feb: 48; Nov: 50; Dec: 33
 National Highway Traffic Safety Administration(NHTSA), Feb: 55; Sep: 75; Oct: 10, 50
 National Institute for Automotive Service Excellence(NIASE), Jan: 56; Mar: 66; Apr: 43; May: 86; Jul: 36, 55; Oct: 63
 National Pit Crew Championship, Aug: 47
 National Tire Dealers & Retreaders Association, Inc.(NTDRA), Sep: 78-79
N-cars (GM), Nov: 53
 NCR Corporation, Sep: 75
 Nerlinger, John W., Jul: 55
 New competition theory, Jan: 7
 NGK Spark Plug Company, Jun: 43
 944 ('83), Jan: 26, 27-28
 Nissan, Jan: 20-22; Feb: 56; Sep: 62.
See also Datsun
 Pulsar NX, Jan: 22; Aug: 63
 Sentra ('83), Jan: 20-22

Ochs, H. Dieter, Aug: 63
 Offenhauser engine, May: 57-60
 Oil leaks, Jan: 62-63; Sep: 92
 Oil pumps, Mar: 47-49; Oct: 57
Oldsmobile, Jul: 38
 cam/fuel pump incompatibility in '76-77s, Dec: 48
 challenge to Ford's position, Nov: 37
 Cutlass ('81), May: 10, 75
 Cutlass Ciera tune up specs, Jan: 74
 Delta 88, Jul: 38
 diesel ('81), whistling noises, Oct: 61
 Misar, ignition timing, Mar: 37
 Multi-Function tone generator failure in '78s, Apr: 10-11
 sales strategy, Mar: 65
Omni (Dodge)
 carburetor mounting, Feb: 9
 disc brake piston, Sep: 88
 disc brake service, Dec: 49
 distributor pickup, Feb: 62
 front suspension noise, Jun: 35
 isolator plates, Jul: 10-11
 mileage problems, Mar: 12, 56
 rear brake noise, Jun: 66-67
 throttle shaft wear, Oct: 12
 transaxle problems, Oct: 60
 vacuum leak, Jul: 10-11

1983 Index

wheel bearing failure, Jan: 61
Opel, transmission fluid for, Sep: 32
Original equipment(OE) suppliers,
Oct: 42
Oscilloscope tests, May: 78

P

Paint, Body & Equipment Association, The, Mar: 59
Paint protectors, Jan: 64
Partially Stabilized Zirconia(PSZ),
Dec: 44
Parts (general information)
aftermarket, ID marking, Mar: 64
for early Porsches, Dec: 64
generic names for, Mar: 64
gypsy, Mar: 66
higher-priced, May: 84
interchangeable, Apr: 38
original equipment, Dec: 34
overseas sources, Nov: 35
recycled, Mar: 82; Jun: 51
replacement, Mar: 68, Jun: 52; Oct:
41; Dec: 34
used, dwindling supplies, Feb: 54
Parts (specific), supplies, accessories
AC condensers, Dec: 64
anti-theft device, Nov: 61
automatic transmission fluid
conditioner, Dec: 61
bearings, Nov: 69
brake lathe parts, Dec: 69
clips and fasteners, Dec: 58
cooler, Sep: 95-96
"courtesy check" tags, Nov: 66
distributor caps, Nov: 59
electrical accessories, Sep: 94
exhaust line, import, Nov: 65
fuse holder, Dec: 66
glow plugs, Dec: 62
oil coolers, Sep: 98-99
rack and pinion units, remanufactured, Aug: 72
radiators, Dec: 60
replacement gas-charged lift
supports, Dec: 60
re-ring kits, Feb: 48
seal interchange guides, Jun: 69
seals, Nov: 69
shock absorbers, Oct: 75-76; Nov: 60;
Dec: 58
spark plugs, Nov: 64-65
spark plug wires, Oct: 72
strut cartridges, Nov: 64
thermostat, replacement, Dec: 63
transmission sleeves, Oct: 71-72
V-belts, Aug: 71; Dec: 62
warning systems, Oct: 68-69
Water Watcher and Remote Discharge Valve, Nov: 61-64
Parts industry
counterfeitors and, May: 85
GM/Toyota venture and, Apr: 35

Japanese, Dec: 35
private branding, May: 84
use of robots by, Jul: 52
Pascal's Law, Dec: 27
Perry, Harold A., Jul: 55
Petty, Richard, Jun: 76
Peugeot, Mar: 88, Sep: 32
Phone support, Dec: 36
Pistons
damage from detonation, Mar: 70, 73
markings in Escort/Lynx, Oct: 61
Pit crew competition, Aug: 47
Plymouth
ignition problems, Jan: 10, 15
Miser ('82-'83). See Miser
(Plymouth)
pistons, pins, rings, crankshaft, and
bearing specs, Nov: 70
Reliant. See Reliant (Plymouth)
vans ('79-'82), starter relay, Jun: 67
Voyager, front/rear a/c, Jun: 19
Plymouth-AAA Trouble Shooting Con-test, Oct: 64
Pcock, Gordon, Aug: 64
Polimotor Research, Nov: 8-9
Polishing, Mar: 55
Pontiac
oil filter bypass valve ('77-'83s),
Jun: 67
radial tire replace, Mar: 90
Pontiac Fiero, Feb: 47; Sept: 16, 20-21,
75, 78; Oct: 49
Pontiac Firebird ('82-'83), radio
replace, Mar: 90
Pontiac 1000, starting motor, tune up,
and wheel alignment specs, May:
106
Pontiac 2000, 50 mpg EPA rating,
Jan: 51
Pontiac 6000, knocking noise, Dec:
49
('82-'83), tune-up specs, Jan: 74
Pontiac Phoenix ('83), thermostat
housing sealant, Sep: 88, 90
Pontiac THM 700-R4, TCC solenoid
wire, Aug: 75
Pontiac T1000 ('81), burned valves in,
Jun: 55
Porsche
cooling system and capacity data,
Feb: 80
1983 models, Jan: 27-28
parts for early, Dec: 64
transmission fluid for, Sep: 32
tune up specs, Feb: 80
Ported vacuum advance, Oct: 38
Positive Crankcase Ventilation (PCV)
system, Jan: 41-44
Posters, pin-up, Dec: 36
Potholes, Jan: 52
Precision Universal Joint Corporation,
Jul: 53
Preheated intake air system, Jan:
46-49
Prelude ('80), shifting, Dec: 54
Pressure plate inspection, Sep: 49-50

Pressure washer, Mar: 83; Jul: 67
Prices, dealer and, Jul: 35
Private branding, May: 84
Probe IV (Ford), Feb: 47
Project START(Service Technician
Advancement Recruitment &
Training), mechanics' self-image
and, Feb: 55
Pro Trac Tire, Jul: 55
Pulse Air Injection(PAIR) system, Jun:
30, 59-61
Pumps
auxiliary, in Toyotas, Mar: 49
in-tank, Jul: 32
oil, in Hondas, Oct: 57

Q

**Quadrajet M4M series adjustment
specs, Sep: 102**
Quota imports, Oct: 43

R

Racing, Feb: 47; Dec: 41-43
Rack and pinion steering, sluggish,
Sep: 10
Radar reading, Jul: 54
Radiators
of Escort/Lynx/LN7, May: 41-42
knock, in Volvo 240 and 260, Jul: 59
rebuilding, May: 41-46, 92
cleaning core, May: 46
core repair, May: 46
tank removal and replacement,
May: 42-46
testing procedure, May: 46, 92
Ram 50, upper control arm replacement, Feb: 80
Ranking, car company, Nov: 36
Raybestos, Aug: 56
Raymark Corp., Mar: 59
Rear-wheel vs. front-wheel drive, Jul:
37
Recalls
carmakers' against, Aug: 52; Dec: 35
of GM pickups and 4 X 4's, Feb: 64
of X-cars, Sep: 6, 63
Reliant (Plymouth)
chuckling noise, Sep: 88
front suspension noise, Jun: 35
rear brake noise, Jun: 66-67
transaxle problems, Oct: 60
Renault
transmission fluid for, Sep: 32
VESTA research vehicle, Feb: 47
wiring abrasion, Dec: 54
Repairs, cost of, Aug: 61
Republic Parts, Apr: 37
Resonators, Oct: 48
Respirator systems, Apr: 65
Rest pressure test, Jul: 30

1983 Index

Restraints, passive, Oct: 10, 50-51
 Rexnord, Inc., Dec: 47
 Robert Bosch GmbH, Jun: 41
 Robertson, A. Barclay, Aug: 63
 Robot(s), May: 86; Jul: 17-20, 52
 Robot Institute of America(RIA), Jul: 19
 Rochester 2SE and E2S3 adjustment specs, Apr: 70
Rolls-Royce, Jun: 54
 Rota, Ray E., Aug: 63
 Rothsmans-Porsche 956, Jun: 41
 RTV silicone sealers, Dec: 23-25
 Run-on, Jul: 21
 Russell, Thomas F., Mar: 42
 Rustproofing, caution in, Dec: 49

S

Saab

99 ('72), frozen cylinder head, Aug: 11
 sales, May: 67; Aug: 62
 service bulletin no. 04/83-624, Sep: 10
 starting problems, Dec: 54
 transmission fluid for, Sep: 32
 Turbo Cabriolet, Dec: 44
 Turbo special edition, Mar: 57
 valve clearance check, Jul: 59
 warranty, Jul: 53
 S-A Design Publications, Jun: 76
 Sanding, Mar: 54; Apr: 65
 Sales, Jan: 18; May: 67; Jul: 38; Aug: 61, 62; Dec: 18, 45
 Sattler, Raymond, Jul: 49-51
 Saturn, Dec: 33, 34
 Schwoebel, James D., Aug: 63
 Sealants, May: 39; Jun: 69; Dec: 23-25
 Seat belts, Jul: 59; Oct: 10, 50-51
 Sebek, Paul, Aug: 64
"Service Slants"

Alliance

shift rod adjust in '83s, May: 90
 transaxle problems in '83-'84s, Nov: 56

Aries/Reliant

chuckling noise in '81-'82s, Sep: 88
 rear brake noise in '81s, Jun: 66-67
 transaxle problems in '81s, Oct: 60

Buick ('80-'81) light throttle detonation, Jul: 57

Cadillac ('81)

cold engine noise, Jun: 66
 MAP sensor line icing, Jan: 61

Chevrolet

dwell reading in '81s, Oct: 61
 EGR valves in '83s, Sep: 88

Chryslers

accelerator pump adjust, May: 91
 differential fill plug in FWD automatic transmission, Aug: 75
 hesitation or sag in trucks, Dec: 49
 ignition components, digital circuit,

Apr: 62
 manual transaxle in '83s, Feb: 64
 power steering shudder in FWDs, Jul: 57
 2.2 liter oversize camshaft markings, Oct: 61
 valve spring change in '81-'83s, Aug: 75
Corvette ('85-'79) disc brake service, Oct: 61
 diesel fuel, contaminated, Dec: 48
Dodge vans ('79-'82), inoperative starter relay, Jun: 67
Escort/Lynx
 brake booster replace, Jul: 57
 piston markings in '81-'83s, Oct: 61
 power lack in '82s, Sep: 88
 steering wheel return in '81-'83s, Jul: 57
EXP/LN7 brake booster replace, Jul: 57
Fairmont/Zephyr
 brake caliper changes in '79s, Jun: 66
 stalling while parking in '81s, Dec: 48
Ford
 a/c spring lock couplings in '81-'83s, May: 90
 detonation problems in '80s, Sep: 90
 FM radio interference in '77-'81s, Oct: 61
 460 cid engines main bearing knock in '75-'77, Aug: 75
 full-lock turn stalling in '78-'81s, Sep: 90-91
 power rack and pinion replacement parts in '79s, Mar: 68
 strut diagnosis, Jan: 61
 3.8 liter engine spark plug change, Feb: 62
GM
 diesel fuel filter test, Sep: 91
 diesel injection pump fuel shutoff solenoid, Dec: 49
 distribution service for HEI ignition equipped, May: 91
 ECM malfunction in '82-'83 diesels, Sep: 91
 restricted exhaust in '82-'83s, Dec: 48
 THM 200-4R buzzing, Dec: 49
 THM 700-R4 gear failure in '82-'83s, Oct: 61
 2.5 liter gear noise, Nov: 56
 wheel failure in pickups and 4 X 4s ('82), Feb: 64
Granada/Cougar ('81)
 rear shock clunking noise, Dec: 49
 stalling while parking, Dec: 48
 HEI ignition mounting screws, Jul: 57
 hot restart problems in diesels, Feb: 62-64
 hydraulic lifters, noisy, Feb: 62
Impala/Caprice ('81 diesels) diode service, Dec: 49
Jeep ('81) water pump and fan assembly, Mar: 68, 72
LeBaron/400 chuckling noise, Sep: 88
LeSabre/Electra ('80) blower motor problems, Dec: 49
Lincoln/Mercury
 power rack and pinion replacement parts, Mar: 68
 full-lock turn stall, Sep: 90-91
 strut diagnosis, Jan: 61
Miser ('82-'83) spark knock, Mar: 68
Mustang/Capri
 brake caliper changes in '79s, Jun: 66
 fluid check, Nov: 56
 stalling while parking, Dec: 48
Oldsmobile
 cam/fuel pump incompatibility in '76-'77s, Dec: 48
 diesel ('81) whistling noise, Oct: 61
Omni/Horizon
 disc brake piston in '83s, Sep: 88
 distributor pickup, in '78-'79s, Feb: 62
 front disc brake service for '78-'83s, Dec: 49
 rear brake noise in '81s, Jun: 66-67
 transaxle problems in '81s, Oct: 60
 wheel bearing failure in '78-'80s, Jan: 61
Phoenix ('83) thermostat housing sealant, Sep: 88, 90
Plymouth vans ('79-'82) inoperative starter relay, Jun: 67
Pontiac
 oil filter bypass valve in '77-'83s, Jun: 67
 6000 ('83) knocking noise, Dec: 49
 THM 700-R4, TCC solenoid wire, Aug: 75
 rustproofing, caution in, Dec: 49
Skylark ('82) insufficient a/c, Apr: 62
Tempo/Topaz ('84) oil spill-over, Oct: 61
THM 200-4R transmission noise, Apr: 62
 valve guide and stem wear, Oct: 60
 welding, galvanized and Zincrometal, Jan: 61
Service Station Dealers of America, Inc., Mar: 59
760 GLE ('83), Jan: 27
Shelby-Chrysler Performance Center, Jun: 76
 Shell Oil Co., gas sales policy, Jan: 51
 Shock absorbers, Dec: 49
 Showich, Nicholas A., Aug: 63
 Siekierda, John T., Jul: 55
Sierra, Jul: 36
 Silencer bands, Jun: 68
 SKF Industries, Inc., Oct: 44; Dec: 47
Skylark (Buick) insufficient a/c, Apr: 62

1983 Index

rear suspension squeaking, Jun: 36
Small Business Motor Fuel Marketer
 Preservation Act, Jun: 41
 Smart, Robert A., Jr., Aug: 63
 Smith, Glenn, Aug: 64
 Smoot-Hawley tariff, Mar: 8
 Smyrna plant, Dec: 33
Society of Automotive Engineers, Feb:
 56; Aug: 14-18
 Solenoid, a/c, Jul: 21
 Somerset, Jul: 37
 Spark advance vacuum modulator
 (SAVM), Oct: 38-39
 Spark knock, Mar: 68, 70, 73, 81-82;
 Sep: 64
 Spark plugs, Feb: 62; Mar: 73
 Specialization, Apr: 44; Sep: 61
 Speed limit, Dec: 35
 Sperlich, Harold K., Sep: 26
 Sports car, children's, Jul: 66
 Sportsman, front/rear a/c, Jun: 19
St. Regis ('79), torque converter
 clutch slippage, Feb: 10-11
Starlet ('81-'83), self adjusting
 clutch, Dec: 53
 Steele, H. William, Jul: 55
Steering
 column, Toyota, Mar: 49-50
 power, in Chrysler FWD, Jul: 57
 rack and pinion, Sep: 10
 "Steering and Suspension Update,"
 Jun: 35-37
 Stempel, Robert C., Sep: 21
 Stu Evans Lincoln-Mercury Southgate,
 Inc., Oct: 22
 Styling, Jan: 52
Subaru
 BRAT, Sep: 75
 FWD, Sep: 62
 GL Brat ('83), May: 69
 transmission fluid for, Sep: 32
 Sun Electric, Jan: 55
Suspension systems. See also
 MacPherson struts
 air, for Mark, Apr: 45
 electronic, Dec: 45
 front end noise in Omni/Horizon,
 Jun: 35
 in Skylark, Jun: 36
Suzuki, hatchback, Nov: 53

T

Tax(es), Jun: 54; Nov: 37
"Tax Tips"
 business mileage, Jul: 68-69
 education expenses, Feb: 74-77
 equipment
 loss coverage, Feb: 73-74
 used, Sep: 83, 87
 fraud, Dec: 56-57
 home-office deductions, May: 102-103
 insurance, business interruption,

Nov: 57-58
 investment tax credit, Sep: 83, 87
T-cars, Feb: 55
 Team service, Oct: 21-23, 54
 Temperature control, electronic, Nov:
 42-44
Tempo (Ford), Apr: 26-31, 59
 chassis, Apr: 59
 diesels, Jul: 38; Sep: 39
 drive train, Apr: 28-31, 59
 introduction, Jul: 54
 marketing of, Apr: 31
 oil spill-over, Oct: 61
 1.6 liter engine option, Jan: 58
 performance engines for, Sep: 62
 support, Nov: 53
 towing, May: 83
 Terrestrial crisis theory, Jan: 6
Tercel (Toyota)
 self adjusting clutch, Dec: 53
 wagon ('83), Jan: 20
Throttle body fuel injection(TBI), Mar:
 33; Sep: 26
 Thrust bearing, Jul: 12-13; Oct: 57
Thunderbird (Ford)
 fluid check, Nov: 56
 hot starting problems, Nov: 10
 thrust bearing wear, Jul: 12-13
 Turbo Coupe ('83), Apr: 31, 59-60
 Tie-rod testing, Mar: 12
 Timing, May: 20, 78; Oct: 37-38. *See*
 also Ignition systems, timing
 procedures
Tires
 bead sealers, May: 98
 P8 (Pirelli), Jan: 52; Mar: 58
 radial, Mar: 57, 90; Jun: 37
 Tool makers, Detroit and, Jan: 55
Tool(s), repair kits, equipment
 abrasive rolls, Apr: 65
 air tank kits, Jul: 66
 analyzers
 starting and charging system,
 Aug: 67
 engine, Oct: 43
 assembly tools, Sep: 95
 battery cable repair kits, Dec: 68-69
 battery chargers, May: 98
 bits, May: 98; Jun: 23
 body repair tools, Jan: 68
 brake, rear, adjuster repair kits,
 Aug: 67
 brake bleeders, Mar: 75; Jun: 69;
 Dec: 28
 brake caliper rubber seal spreader,
 May: 77
 cabinets, Feb: 47; Dec: 63
 camber correction tool, Mar: 75
 carburetor floats, Dec: 68
 charging stations, Jun: 68
 cleaners, Dec: 66
 brake, Feb: 68
 degreaser and engine, Dec: 60
 electrostatic precipitator air, Nov:
 69
 hand, Jan: 72
 liquid tar and bug remover, Dec: 59
 solvent, Oct: 73
 cleaning tanks, Aug: 69-71
 collision repair system, Dec: 61-62
 compressor
 air, Mar: 82-83
 methane, Feb: 58-59
 cooling system flusher, Oct: 77
 crankshaft stroke gauge, Oct: 74
 creepers, Mar: 84; Jul: 67
 crimping tool, Nov: 59-60
 cut-off, air-operated, Apr: 64
 cutting tools, Sep: 10
 drills
 angle, Jun: 22
 bits, May: 98; Jun: 23
 cordless, Mar: 75
 dynamometer, liquid nitrogen-cooled,
 Dec: 44
 expanders, piston ring, Jun: 72
 flashlights, Vari-Beam, Jun: 23
 fusepuller, Jun: 22
 gasket material, Nov: 65
 grease, high temperature, Dec: 67
 hammers, dead blow, Jun: 22
 hitch receivers, Oct: 72
 hoists, chain, Jun: 72
 hole saw kits, Jun: 68
 hose reels, Aug: 72
 hydraulic puller, Sep: 97
 impact tools, Oct: 77
 injector tool kit, Nov: 60
 inspection lights, Nov: 67-69
 jacks, hands, Oct: 69-70
 lamp kits, Jul: 66
 lathes, brake
 centering cone, Sep: 97
 combination, Jan: 68
 disc, Nov: 61
 molding guide, Jun: 23
 muffler stand, Oct: 76
 nut starter, Jun: 22
 piston-engine borescope kit, Oct:
 76-77
 primers, aerosol, May: 98
 pulley set, Oct: 71
 pump transfer, Nov: 66-67
 radial compressor conversion kits,
 Sep: 96
 reverse clutch housing remover,
 Mar: 77
 sander grinder, Sep: 99
 Sav-A-Thread, Jun: 22
 screwdrivers, May: 99; Jul: 65;
 Dec: 64
 separator, fuel/water, Dec: 67-68
 solvent wipes, Jan: 64
 spray booths, Jan: 64; Dec: 66
 stand and crane, Sep: 96-97
 surface lift, Oct: 74
 tachometers, Oct: 70-71
 tapes
 attachment, Oct: 69
 self-adhering safety, Dec: 69
 TBI(throttle body fuel injector)
 repair kit, Dec: 66

1983 Index

- telephones
 coin-operated, Dec: 66-67
 cordless, Dec: 59
- temperature probes, Aug: 68
- testers
 C-3, Apr: 22-25, 52-57; Dec: 63-64
 Chrysler electronic engine control system (Part #C4805), Nov: 26
- Custom III Cruise Control System, Dec: 60
- cylinder leakage, Dec: 69
- dye-penetrant, kit, Oct: 75
- ignition module/voltage, computerized, Dec: 61
- module, Oct: 68
- timing kits, Dec: 64
- tire repair kits, May: 99
- torsion spring twister, Jun: 23
- transmission tools, Aug: 67
- tubing kit, Jul: 66
- vacutector, Aug: 71-72
- vacuum
 asbestos, Feb: 68; Dec: 69
 pumps, Jun: 22
- vehicle detector, Dec: 58
- volt/amp meter, Sep: 94
- welders, Aug: 68-69
 MIG, portable, Dec: 69
 push-pull gun, Dec: 62
 spot/pulse, Jul: 67
- wheel aligners, Jan: 69; Jun: 69;
 Sep: 94; Oct: 69
- wheel balancers, Mar: 85; Jul: 67;
 Sep: 95
- windshield repair kits, Jan: 73
- wreckers, May: 99
- wrenches
 air control valve, Dec: 66
 strut, Sep: 99-100
- Topaz (Mercury)**, Apr: 26-31, 59
- chassis, Apr: 59
- diesels, Jul: 38; Sep: 29
- drive train, Apr: 28-31, 59
- introduction, Jul: 54
- marketing of, Apr: 31
- oil spill-over, Oct: 61
- 1.6 liter engine option of, Jan: 58
- performance engines for, Sep: 62
- support, Nov: 53
- towing, May: 83
- Torx keys, Jul: 66
- Toyo Kogyo, Apr: 45
- Toyota**
 automatic transmission, May: 94-96;
 Jun: 63-65
 auxiliary pumps, Mar: 49
 Camry ('83), Mar: 57
 distributor rotors, Sep: 82
 electronic ignition system points,
 Mar: 46
 Celica, Jan: 20
 Cressida, Jan: 20; Mar: 46
 1983 imported cars, Jan: 20
 oil filter repair, Mar: 50
 seat belt relay in '74s, Jul: 59
 service problems, Mar: 45-50
- starter replace, Nov: 70
- steering column, Mar: 49-50
- throttle cable adjust, May: 94
- Supra ('81-'82), Jan: 20; Mar: 46
- Tercel. *See Tercel (Toyota)*
- transmission fluid for, Sep: 32
- Toyota-GM partnership**
 Chrysler and, May: 83
 "foreign imports" and, Apr: 38
- in-house reactions, Sep: 60
- Japanese production secrets and,
 Apr: 36
- negotiations, Jan: 57
- parts business and, Apr: 35
- possible consequences of, Dec:
 34-35
- Trade, international, loca content
 legislation vs., Mar: 8
- "Trade Secrets"**
 Cadillac ('81) power steering/power
 brake problems, Mar: 16, 67
 check guarantee service, Mar: 67
- Chrysler ('79) aspirator valve failure,
 Nov: 18-19
- Colt ('80) catalytic converter, Dec: 14
- customers, flexibility with, Jun: 12
- Cutlass ('81) C-3 engine control
 system, May: 10, 75
- driver characteristics and warranties,
 Sep: 12, 67
- Oldsmobile ('78) Multi-Function tone
 generator failure, Apr: 10-11
- Plymouth ('75) ignition problems,
 Jan: 10, 15
- St. Regis ('79) torque converter
 clutch slippage, Feb: 10-11
- thrust bearing wear, Jul: 12-13
- Torque Flite transmission problems,
 Aug: 12-13
- Vega ('77) overheating, Oct: 16, 53
- Transaxles**
 A-460, Oct: 60
- in Alliance ('83-'84), Nov: 56
- in Aries/Reliant ('81), Oct: 60
- manual, in Chrysler ('83), Feb: 64
- oil change recommendations for '83
 Chryslers, Feb: 64
- in Omni/Horizon, Oct: 60
- Transmissions**
 automatic, Toyota, May: 94-96; Jun:
 63-65
- auxiliary, Jul: 65
- bearings, noise test for, Sep: 48-49
- filters, Sep: 31-41
- fluid, Sep: 32, 41-42
- gear rollover test, Sep: 48-49
- T-5, Nov: 56
- THM
 leak diagnosis, Dec: 55
- 200-4R noise, Apr: 62
- 700-R4, TCC solenoid wire, Aug:
 75; Oct: 61
- Torque Flite, Jan: 8; Aug: 12-13
- Toyota 5-speed, Mar: 49
- tuneups, Sep: 31-44
- filters and, Sep: 31-41
- intervals, Sep: 41-42
- Triple A, Oct: 44
- Triumph, transmission fluid for, Sep:
 32
- "Troubleshooter"**
 Aspen ('77)
 brake bind, May: 8
 cold running, May: 8
 front wheel lock up, Feb: 8
- Cadillac Sedan DeVille alignment
 problem, Jan: 8-9
- Chevette
 fuel system, in '79s, Aug: 10-11;
 Nov: 10
- Hatchback ('80) steering wheel
 shakiness, Feb: 8
- Chevy 3.8 liter cold driveability
 problems, Dec: 12-13
- Chryslers, cold driveability problems,
 Aug: 10
- CIS hot start problems, Oct: 12, 52
- EEC IV computer-equipped Fords,
 timing adjusts, Jun: 10
- Econoline ('61) van generator light
 problems, Jun: 55
- Fairmont ('79) driveability and
 stumble problem, Apr: 8; Jul: 10
- float bowl fuel loss, Jul: 10
- Ford F350 ('79) fuel vaporization
 problems, Nov: 10-15
- Ford van ('78) fuel vaporization
 problems, Nov: 10-15
- head gasket retorquing, Oct: 52
- LUV ('74) pickup linkage, Jan: 9
- Malibu
 mixture problems, Sep: 64
- pinging, Jun: 10, 55
- Monaco ('77) handling problems,
 Feb: 8-9
- Nova ('68) oil dilution problem,
 Apr: 8-9
- Omni/Horizon
 carburetor mounting, Feb: 9
- isolator plates, Jul: 10-11
- mileage problems, Mar: 12, 56
- throttle shaft wear, Oct: 12
- vacuum leak, Jul: 10-11
- Pontiac T1000 ('81), burned valves,
 Jun: 55
- rack and pinion steering, sluggish,
 Sep: 10
- Saab 99 ('72) frozen cylinder head,
 Aug: 11
- spark knock, Sep: 64
- Thunderbird ('68) hot starting
 problems, Nov: 10
- tie-rod testing, Mar: 12
- Torqueflite transmission trouble,
 '79 Plymouth, Jan: 8
- Trucks**
 sales, Dec: 45
- turbocharged diesel, Apr: 14-18,
 46-50
- Truth in Lending Act, Apr: 6
- Tuneup(s)**, May: 15-21, 78-79
- average cost of, Apr: 38

1983 Index

cold start comebacks, May: 20
diagnostic routine, May: 15-20
power balance, May: 78-79
scope reading, May: 78
spark timing tips, May: 20, 78
Tune-up Manufacturers Institute
(TMI), Sep: 78
TVR Tasmin, Jun: 46
Type F transmission fluid, Sep: 32

U

Ultra, Aug: 61
Unemployment figures manipulation,
Oct: 43
Unit body cars, metal repair problems,
Mar: 65
United Parts Division of Echlin, Inc.,
Mar: 57
Used equipment, Sep: 83, 87

V

Vacuum breaks, Jul: 23-24, 28-29
Vacuum spark control devices, Oct:
37-39
Valve(s)
auxiliary, in Hondas, Oct: 32, 56
burned, in T1000, Jun: 55
deceleration, Jul: 21-24
distributor vacuum delay(DVDV),
Oct: 39
EGR, Feb: 19-20, 21; May: 20
thermal vacuum(TVV), Jan: 20
vacuum reducer(VRV), Oct: 38
Valve guide and stem wear, Oct: 60

Vanagon (Volkswagen) water-cooled
engine, Jul: 63-64
Van Wagon, Nov: 50
Vapors, gasoline, danger of, Oct: 63
Vehicle Multiple Listing Network
(VMLN), Jul: 53
Vehicle theft, Feb: 54
Volkswagen
ignition timing procedures, Mar: 41
Jetta, Jan: 27
1983 models, Jan: 26-27
retail leasing by, Jul: 53
3508 mpg car, Jan: 51
transmission fluid for, Sep: 32
Volkswagen-Chrysler deal collapse,
Oct: 42
VW Quantum ('83), Jan: 27
VW Rabbit
Diesel ('83), Jan: 27
80 mpg, Jan: 12
front end clunking noise, Dec: 53
GTI ('83), Jan: 24, 26-27
VW Vanagon, water cooled engine,
Jul: 63-64
Volvo, Jan: 27; **Mar:** 58
clutch repair in '79s, Sep: 50
140, sump removal, Sep: 82
transmission fluid for, Sep: 32
240 and 260, radiator knock, Jul:
59

W

Wagner, Mar: 58; **Aug:** 56; **Dec:**
45-46
Walker Manufacturing Company, Mar:
59; Jun: 43
Warehouse distributors, discounts

offered by, Apr: 36
Warranties, driver characteristics and,
Sep: 12, 67
Wastegates, turbocharger, checking,
Sep: 53-56
Weed Currie, Oct: 54
Welding
clamping vs., in exhaust systems,
Oct: 48
contact lens use and, Jun: 52; Jul: 37
of galvanized or Zincrometal panels,
Jan: 61
Westfield Sports Cars, Jul: 53
Weston, Richard, Aug: 63
Whitehead, Lewis E., Jr., Oct: 23
Windows, power, May: 98
Windshield wipers, neglect of, Jan: 51
Winnebago Industries, Jun: 43
Wolter, James G., Jul: 55
Working conditions, mechanics', Feb:
6-7
Worth Manufacturing, Nov: 53

X

X-cars (GM), Apr: 35, 37
clutch repair tips, Sep: 45-48
brake problem in, Aug: 6-7
recall, Sep: 6, 63

Z

Zephyr (Mercury)
brake caliper changes, Jun: 66
stalling while parking, Dec: 48
Ziebart, Aug: 54

